



Update Prior to Sale Notice

Issue Date **23 October 2007**

Expiry Date **23 April 2008**

Action No **UPS 3307-1**

To **For the attention of All Land Rover UK Dealers, National Sales Companies and Importers excluding North America**

Attention Managing Director and Aftersales/Service Director

Model **2008MY Range Rover Sport V8 Diesel
VIN Range LS 133990 to LS 144704 (specific vehicles)**

Subject **Radiator Upper Hose Clip**

Information Quarantine in Dealer or applicable NSC location.

The Update Prior to Sale Notice is valid for six months only. Repairs must be complete prior to the expiry date at the top of this Update Prior to Sale Notice.

Dear Colleagues

Issue

A concern has been identified with the radiator upper hose clip on a limited number of 2008MY Range Rover Sport V8 Diesel vehicles which may result in coolant loss and the possibility of the engine overheating.

Action to be taken

You are requested to quarantine the affected vehicles that are in your control and refrain from releasing the vehicles for onward distribution and sale pending completion of the rework action detailed in this Update Prior to Sale Notice.

The affected vehicles should not be released until the rework procedure has been completed.

The workshop procedure is attached as Appendix 1. On completion of the rework procedure, the vehicle may then be released from quarantine for onward distribution and sale.

A number of vehicles have been reworked at the factory prior to dispatch and can be identified by a windscreen label bearing a red letter 'H'; no further action is required on these vehicles.

DDW will be updated to reflect only those vehicles affected. Should you require a list of the affected vehicles please contact the Land Rover Field Actions Team by e-mail at jlrcamp@landrover.com. All requests should be forwarded via the National Sales Company/Regional Office only.

This update prior to sale notice affects vehicles in your control only.