

## **Repairs Carried Out On Range Rover WBD940**

- \*Steering column rattle – Removed and replaced steering angle sensor.
- \*Clunk from suspension/steering – Removed and replaced front lower Ball joints.
- \*Battery going flat – tested for battery drain and condition, unable to Fault.
- \*Interior dash console trim adrift – Replaced securing clips & refit trim.
- \*Check for car pulling left – Road test and unable to fault.