

[Steering_wheel_blister.jpg](#)

Reference SSM33946

Models Discovery 3
Range Rover Sport

Title Discovery 3 /LR3 & Range Rover Sport Steering Wheel
Peel/Wrinkle

Category Body

Last modified 26-Oct-2007 00:00:00

Symptom 107000 Interior Trim

Potential concern: Discovery 3 / LR3 and Range Rover Sport customers in hot climate markets only, may report the Steering wheel leather cover becoming sticky, wrinkly and / or peeling off. The attached picture displays the condition.

Action: A limited number of modified condition replacement steering wheels are available through Caterpillar and must be replaced only on a 'fix on complaint' basis for this concern. Please do not stockpile parts.

The Replacement Steering wheel Part numbers are:
LR 006967 - No Cut out
LR 006968 - L/H Cut out for 'Push to talk Switch'
LR 006969 - L/H & R/H Cut out for 'Push to talk' Switch & 'Phone End call' Switch'

