

## LAND ROVER



Our ref Recall:

Vin:

Reg:

Date: 12/06/2006

## **IMPORTANT**

## 2005/6MY Range Rover Sport vehicles with 19inch wheels SAFETY RECALL

Subject: LH Front Brake Flexi Hose Chafe

Dear Sir/Madam

Land Rover is undertaking a no-charge Safety Recall (Program Number A039) to owners of 2005/6 Model Year Range Rover Sport vehicles with 19-inch wheels.

Reason for this program

During certain manoeuvres when the steering system is on full left lock and the suspension is moving towards full compression, the left front brake hose and/or the ABS wheel speed sensor lead and/or the brake pad wear warning sensor lead can catch on the wheel balance weight as the wheel rotates. This may lead to premature brake pad wear warnings, warnings of ABS failure, or extended brake pedal operation.

What Land Rover and your dealer will do

Land Rover is carrying out a voluntary recall of the vehicles mentioned above. Land Rover Dealerships will replace the clip on balance weights fitted to your vehicle with stick on balance weights. In addition the left front brake hose, ABS wheel speed sensor lead and the brake pad wear warning sensor lead will be inspected for damage and where necessary replaced.

How long will it take?

The work will be carried out as quickly and efficiently as possible in order to minimize inconvenience to customers and is expected to take no longer than one hour, although your dealer may need your vehicle for a longer time due to service scheduling requirements.

What we are asking you to do

Contact your preferred Land Rover dealer without delay. Provide the dealer with your Vehicle Identification Number (VIN) (located at the beginning of this letter) and vehicle registration number. Ask for a service date for Recall Program A039. If you do not have a servicing dealer, please access www.landrover.com for dealer addresses, maps, and driving instructions.





Land Rover

Banbury Road, Gaydon Warwick CV35 ORR England

Telephone 01926 641111 Facsimile 01926 641587 www.landrover.com

Registered Office: Banbury Road, Gaydon, Warwick CV35 ORR Registered in England and Wales: Number 4019301

