

Confirmation of Service

*Registration No: WBD 940 *Date 9/12/09

Odometer Reading: 22053

*Member's signature: [Signature]

- Checked Oil Level
- Checked Coolant Level
- Electrical System
- Ignition System
- Fuel System
- Cooling System


Additional Information:

Suspected power steering
wack causing fluid
pressure noise

Cross area of work completed:

Lockout ⇒

Wheel Change ⇒



Battery Test Results:

- Pass/OK
- Replace
- Charge & retest

Vehicle charge rate: Volts: _____ Amps: _____

Your battery is in a low state of charge:
Driving the vehicle over any distance will not sufficiently
recharge the battery. Please recharge and retest your battery.

Radio operating on arrival: Yes

No, your radio code appears to have been lost due to the low
charge of your original battery. Reset procedure as per owners
manual or contact your dealership to confirm code.

THE ABOVE RECORDED FAULTS SHOULD BE CONFIRMED BY
YOUR REPAIRER PRIOR TO REPAIRS COMMENCING

* Field must be completed